## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2014 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING <b>01</b>			(X3) DATE SURVEY COMPLETED	
155787			B. WING			09/22/2014	
NAME OF PROVIDER OR SUPPLIER  INDIANA VETERANS HOME				385	REET ADDRESS, CITY, STATE, ZIP CODE 51 N RIVER RD EST LAFAYETTE, IN 47906		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SH			(X5) COMPLETION DATE
K 000	0 INITIAL COMMENTS		K	000			
	INITIAL COMMENTS  A Life Safety Code and Environmental Preoccupancy survey for phase 1 of the renovated second, third and fourth floor of MacArthur Hall was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).  Survey Date: 09/22/14  Facility Number: 001134 Provider Number: 155787 AIM Number: 200817200  Surveyor: Mark Caraher, Life Safety Code Specialist  At this Life Safety Code and Environmental Preoccupancy survey, Indiana Veterans Home was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2-3.1-19, Environment and Physical Standards of the Indiana Health Facilities Rules for Comprehensive care facilities.  This facility located in three buildings identified as Mitchell Hall (3 story with partial basement), Pyle Hall (3 story with basement) and MacArthur Hall (4 story with basement) was determined to be of Type 1 (443) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridor and in all areas open to the corridor. The facility has smoke detectors						

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2014 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01			(X3) DATE SURVEY COMPLETED			
		155787	B. WING _			09/	22/2014		
	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE  3851 N RIVER RD  WEST LAFAYETTE, IN 47906					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			(EACH (	VIDER'S PLAN OF CORRECTION CORRECTIVE ACTION SHOULD E REFERENCED TO THE APPROPRI DEFICIENCY)	3E	(X5) COMPLETION DATE		
K 000	hard wired to the fire sleeping rooms. The 197 and had a censu survey.  All areas where resid were sprinklered. All services were sprinklegenerator building an	alarm system in all resident facility has a capacity of s of 150 at the time of this ents have customary access areas providing facility ered except for the detached d maintenance shop.  x Brashear, Life Safety Code	K	00					